

How to install, replace CLT-R406 Imaging Drum reset

Imaging Drum reset chip (fuse)

Work with: Samsung CLX-3300, CLX-3305, CLX-3305FN, CLX-3305FW, CLX-3305W, SL-C460FW, Xpress C460FW, Xpress C460W CLP-360, CLP-365, CLP-365W, SL-C410W, Xpress C410FW, Xpress C410W, Xpress 430w , SL-C480FW

Part Number: CLT-R406-F

Page Yield: 16,000 black/white; 4,000 color pages

Please check the website below for the video instruction

<https://youtu.be/fkQNGeRsLF4>

Or Use your phone to scan the QR Code below

